

## 6.0 LITERATURE CITED

- Army Corps of Engineers. 1956. Interim Report on Umpqua River and Tributaries, Oregon.
- Army Corps of Engineers. 1966. Flood Plain Information Interim Report, Douglas County, Oregon.
- Army Corps of Engineers. 1988. Memorandum reporting flood damage analysis for the Northern Douglas County Cooperative Water Resources Study, Oregon. Portland District.
- Beckham, S.D. and Minor. R. 1988. Cultural Resource Overview of the Proposed Milltown Hill Reservoir, Douglas County, Oregon. Heritage Research Associates, Eugene, Oregon.
- Bureau of Land Management. 1983. Roseburg Timber Management Environmental Impact Statement.
- Bureau of Mines. 1990. Preliminary Mineral Assessment, Northern Douglas County Cooperative Water Resources Study, Oregon (General Investigation Program).
- Bureau of Reclamation. 1956. Reconnaissance Geological Report on Umpqua River Basin Dam Sites Oregon.
- Bureau of Reclamation. 1956. Umpqua River Basin, Oregon, Special Report (Evaluation), Region 1, Boise, Idaho.
- Bureau of Reclamation. 1966. Elk Creek Basin (Yoncalla Division), Umpqua River Project, Salem, Oregon.
- Bureau of Reclamation. 1983. Galesville Project Final Environmental Statement (FES 83-84), July 11, 1983. Boise, Idaho.
- Bureau of Reclamation. 1989. Outlet Works Design for Milltown Dam-Umpqua Project, Oregon.
- Bureau of Reclamation. 1990. Geologic Report for Final Design Umpqua River Project Elk Creek Division Milltown Hill Dam and Reservoir, Boise, Idaho.
- Bureau of Reclamation. 1991. Northern Douglas County Cooperative Water Resources Study. Status Report and Environmental Report.
- Bureau of the Census. 1988. 1987 Census of Agriculture, Advance County report, Douglas County, Oregon AC87-A-019(A), Department of Commerce, Washington, D.C.

- Craven, R. 1989. Fisheries Resources, Habitat Conditions, and Enhancement Possibilities for Elk Creek, Douglas County, Oregon. Campbell-Craven Environmental Consultants, Tigard, Oregon.
- Craven, R. 1990. Analysis of Fisheries Benefits for the Proposed Milltown Hill Reservoir Project, Elk Creek, Umpqua River Basin, Oregon, Campbell-Craven Environmental Consultants, Tigard, Oregon.
- Department of Environmental Quality. 1990. 1989 Oregon Air Quality Annual Report. (305b Report).
- Douglas County Planning Department. 1989. Douglas County Comprehensive Plan, Roseburg, Oregon.
- Douglas County. 1989. Douglas County Water Resources Management Program, Roseburg, Oregon.
- Douglas County Water Resources Survey. 1990. Milltown Dam Project, Hydrology Appendix, Douglas County Water Resources Survey Roseburg, Oregon.
- Douglas County Water Resources Survey. 1991. Irrigation Requirements and Irrigation Return Flow Estimates for Milltown Hill Project, Douglas County, Oregon. Douglas County Water Resources Survey.
- Fagan, John L., 1992. Archaeological Testing of High Probability Areas, Milltown Hill Dam and Reservoir Project, Douglas County, Oregon. Archaeological Investigations Northwest, Report No. 22.
- Federal Insurance Administration. 1979. Flood Insurance Study for the City of Drain, Oregon, U.S. Department of Housing and Urban Development.
- Fish and Wildlife Service. 1990. Impacts to Fish and Wildlife Resources with the Milltown Hill Dam and Reservoir, Northern Douglas County, Oregon, U.S. Fish and Wildlife Service, Portland Field Office.
- Fish and Wildlife Service. 1991. Listed and proposed Endangered and Threatened Species and Candidate Species that may occur in the Area of the proposed Milltown Hill Dam and Reservoir. Letter dated March 28, 1991 to Richard Prange, Bureau of Reclamation from Russell Peterson, USFWS.
- Franklin, J.F., and C.T. Dyrness. 1973. Natural Vegetation of Oregon and Washington. Gen. Tech. Rep. PNW-8. Portland, Oregon: U.S. Department of Agriculture, Forest Service, Pacific Northwest Forest and Range Experiment Station; 417p.

- Geological Survey. 1963. Geology of the Anlauf and Drain Quadrangles, Douglas and Lane Counties, Oregon. Bulletin 1122-0.
- Geological Survey. 1977. Availability and Quality of Ground Water in the Drain-Yoncalla Area, Douglas County, Oregon, Portland, Oregon.
- Hawthorn, F.F., J. Ake and RC LaForge. 1990. Seismotectonic Study for the Milltown Hill Damsite - Umpqua River Project, Oregon. Bureau of Reclamation, Denver, Colorado.
- Hill, Clair A. and Associates. 1968. Elk Creek Project Reconnaissance Report.
- Hill, Clair A. and Associates. 1968. Letter report, June 15, 1968.
- Hill, Clair A. and Associates. 1969. Engineering Geology and Soils for Elk Creek Dam Site, Douglas County, Oregon.
- Hill, Clair A. and Associates. 1971. Feasibility Report (PL-984) on Elk Creek Project Near Drain, Redding, California.
- Horn, D.W. 1990. Descriptions of Facilities Proposed for Milltown Hill Reservoir Recreation Area. Roseburg, Oregon, June, 1990.
- International Engineering Company, Inc. 1978. Douglas County Damsite Investigations. Reconnaissance Report and Cost Estimate.
- International Engineering Company, Inc. 1980. Adams Creek Damsite Preliminary Engineering Report.
- Minor, Rick, and Stephen Dow Beckham. 1990. A Class III Cultural Resource Survey for the Proposed Milltown Hill Reservoir Area, Douglas County, Oregon. Heritage Research Associates (HRA) Report No. 99. Eugene, Oregon.
- Motorola Microwave Field Engineering. 1990. Scott Mountain to Roman Nose Microwave Survey Report for Douglas County, Schaumburg, Illinois.
- Myers, Tucson & Associates. 1991. Loan and Grant Application for Milltown Hill Project, Tucson Myers & Associates, Inc. Silverton, Oregon.
- Myers, Tucson & Associates. 1989. Water Resources Management Program, Douglas County, Oregon, Volume I and Volume II.

Oster, Eugene A., and Swift, C.H. III. 1969. Channel Capacity and Flood Characteristics for Selected Reaches of Elk Creek and Tributaries, Douglas County, Oregon. U.S. Geological Survey, Water Resources Division, Open-File Report.

Oster, Eugene A. 1971. Floods on Selected Reaches of Elk Creek, Douglas County, Oregon. U.S. Geological Survey, Hydrologic Investigations, Atlas HA-388.

Parks and Recreation Division. 1983. Oregon Statewide Comprehensive Outdoor Recreation Plan. Oregon Department of Transportation.

Parks and Recreation Division. 1988. Oregon Statewide Outdoor Recreation Plan 1988-1993. Oregon Department of Transportation.

Robinson, J.H., and Collins, C.A. 1977. Availability and Quality of Groundwater in the Drain - Yoncalla Area, Douglas County, Oregon. U.S. Geologic Survey Water Resources Investigations 76-105, Portland, Oregon.

Roulette, B. Rane Bonnie J. Miller, 1991. Archaeological Assessment of the west side of Area B. Milltown Hill Reservoir, Douglas County, Oregon. Archaeological Investigations Northwest, Portland, Oregon.

Roulette, B.R., John L. Fagan, and Bonnie J. Miller. 1992 Archaeological Assessment of the East Side of Area B and Testing of Site 35D0478, Milltown Hill Reservoir, Douglas County, Oregon. Archaeological Investigations Northwest.